
MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SEC. $36\,\mathrm{TWN}.~15_{n}\,\mathrm{RNG}.~2_{E}$

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



Corner originally set as a post in 1820 By Wm. B. Laughlin with the following witnesses: 13" sugar bearing S 25 W 43 links and a 13" dogwood bearing N 32 E 30 links.(Marion County Atlas p. 2) A survey by H.B. Fatout on October 24, 1882 indicates no stone or witnesses.(Decatur Legal Book p. 25) Corner referenced by Wilcoxen on 9/15/1980 and called a 1x1x2 stone with cut x. Corner referenced by Wilcoxen on 3/22/90 and called a stone found with cut x. Corner referenced by Wilcoxen on 12/17/95 and called a stone found with cut x. Corner referenced by Wilcoxen on 9/10/1996 and called a stone found with cut x. Corner referenced by Taylor on 5/21/09 and called a stone found with cut x.

	H	
REF.	DISTANCE	DESCRIPTION
1.	105.35'	Top nut of fire hydrant
2.	37.92'	Survey marker nail w/ brass washer W 12" walnut tree 4" up
3.	19.98'	Survey marker nail w/brass washer W fence post 4" up
4.	146.31'	Due S to WQ 31-15-3 (5/8" rebar w/ aluminum cap)
5.	16.05'	SE corner of fence post 18" up
6.	25.50'	PK nail w/ brass washer E 25" mulberry 10" up